


**Infrared Survey.com** sample house with water issues  
**Thermographer: John Cannamela 704-200-6367**




Description: 1<sup>st</sup> level entry suspect upstairs tub



**John Cannamela**  
**[www.infraredsurvey.com](http://www.infraredsurvey.com)**


**Infrared Survey.com** sample house with water issues  
**Thermographer: John Cannamela 704-200-6367**



Description: Front door vent blowing on light switch with outside air leakage causing condensation



**John Cannamela**  
**www.infraredsurvey.com**



Description: Front door light switch with condensation evidence.  
Seal opening with gasket

